




Presentation Station Instructions

10/15/13


Parts List

Tools Required


- Screwdriver




1 x8




2 x4




3 x8



4 x4




6 x2



7 x2

1



Alignment of the threaded insert may require a screwdriver.