
























# LUXOR


## Warehouse Powered Workstation Assembly Instructions




# Parts List

<p><b>1X</b></p> 	<p><b>1X</b></p> 	<p><b>1X</b></p> 
<p><b>1X</b></p> 	<p><b>1X</b></p> 	<p><b>1X</b></p> 
		<p><b>5X</b></p> 
		<p><b>1X</b></p> 
<p><b>1X</b></p> 	<p><b>1X</b></p> 	<p><b>1X</b></p> 
<p><b>1X</b></p> 	<p><b>1X</b></p> 	<p><b>1X</b></p> 
<p><b>M8x16 mm</b> <b>10X</b></p>  <p><b>M6x12 mm</b> <b>8X</b></p>  <p><b>M5</b> <b>1X</b></p> 	<p><b>M4x12 mm</b> <b>2X</b></p>  <p><b>M6</b> <b>2X</b></p> 	<p><b>M6x12 mm</b> <b>20X</b></p>  <p><b>4X</b></p>  <p><b>(included in separate box)</b></p> 


# Step 1




# Step 2




### Step 3




### Step 4




## Step 5




## Step 6



## Step 7



## Step 8



# Step 9

